

Ectaber 29, 1979

er. Robert Habler Discond Head (11) Refining Co. 1401 Harrison Turnpike Kaarny, Hew Jersey (17032)

Cear Mr. Mahler:

Or. Michael V. Polito of my staff and Mr. John Eurger of Ecology and Environment, a contractor to the Ceited States Environmental Protection Agency, observed recent spills of oil, as evidenced by fresh glossy accumulations of oil at your leased facility, during their visit of October 18, 1979.

These oil spillages were located to the rear of your office building and also in areas adjacent to the building in which you conduct your oil packaging operation.

These oil spillages were observed to be hydrologically connected to a low property area in which oil floats atop accessiated water which, depending upon the volumes of facility runoff, leaves the Diamond Head property to the waters of the United States.

Unite the Newtown Refining Company has installed a temporary system to attempt to revove such oil, any failure or shortco-ing of this temporary removal system would result in spillages of oil to the waters of the United States.

These spillages were discussed with you during Or. Polito's visit to your facility on duly 10, 1979 and shown to Mr. Daniel L. Martin, Esq., counsel for Mowtown Roffining, who was coordinating energoncy spill response actions at the facility on October 19.

Such releases, if reaching waters of the United States, would result in violation of Public Law 92-593, Section 311, and would be subject to all provisions of this statute and regulations issued thereunder.

You are advised to proceed with all baste to step are spillages of oil and close up past spillages.

If you have any questions concurring this matter, please contact Par. Polito of this office at (201) 321-6652.

Sincerely yours.

Fred A. Rebal Chief. Feergency Pesponse is Inspaction Branch

cc: R. Tisch

T. Ceruise

0. Pertia

J. Brown

10/23/1/1

Gitter 24. 1979

Fr. Robert Mahler Statend Head Oil Roffining Co. 1401 narrison Turquika Asamy. Haw Jorsey C7880

war fr. dahlari

For a character of following staff and fir. John Surgar of Scology and Environment, a contractor to the United States Environmental Protection Agency, observed recent spills of oil, as evidenced by fresh glassy escurplations of oil at your lessed facility, during their visit of October 10, 1979.

These of spillages were located to the rear of your office building and also in areas adjacent to the building in which you consist your oil packaging operation.

These oil spillages were observed to hydrologically connect to a low property area in which cil floats atop accumulated water from which, depending upon the volumes of facility runoff, leave the blamped Haad property to the navigable waters of the United States.

while the Newtown Sefining Company has installed a temporary system to actempt to reverse such oil, any failure or shortcoming of this temporary removal system would result in spillages of oil to the navigable waters of the delted States and tributaries therete.

These spilleges were discussed with you during Fr. Falito's visit to your facility on July 10. 1979 and shown to Fr. Daniel L. Hartin, Esq., counsel for Wewtown Reflicing, who was coordinating exergency spill response actions at the facility on October 19.

Such releases, if reaching navigable waters of the United States or tributaries thereto, would result in violation of Public Law 92-200, Section 311 and would be subject to all provisions of this statute and regulations issued there were.

You are advised to proceed with all haste to stop new spillages of oil and clean up past spillages.

If you have any questions concerning this matter, please feel free to contact me.

Sfacerely years,

Fred &. Rubel Gilef. Cargancy Paspoise a Inspection branch

cc: A. Tisch

T. Garains

3. Sertia

J. Grown

Proposed by the